### **WPC Septage Building**



# Town of Barnstable ADA Transition Plan

August 2021



Institute for Human Centered Design

200 Portland Street, Boston, MA 02114 www.IHCDesign.org • info@IHCDesign.org 617-695-1225 voice/ tty

#### **Background**

The Water Pollution Control Septage (WPC) facility is located at 617 Bearse's Way in Hyannis. Services offered at the WPC include paying for permits and paying bills for all types of water pollution.

**Note:** IHCD team only surveyed the areas where services are offered to members of the public on the first floor. The first floor includes a service counter.

There are two (2) entrances to the building located on the southeast and west sides of the building. Those entrances are not accessible. The parking area closer to the main entrance is at the loading dock - there are no accessible spaces there. The lower parking lot (southwest side) has seven (7) parking spaces – there are also no accessible parking spaces there.

The septic discharge building is also located on site. That building is not open to the public. Although members of the public drive up to that area where the sceptic discharge system is located to empty/clean out waste from RV's, septic tank cleaning companies to empty their tank, etc. If a member of the public needs assistance, a staff person is available to assist.

#### **Key Accessibility Issues**

- Ramp located on the northwest side of the building has an excessive slope and lacks compliant handrails.
- The entrances/exits are not accessible.
- The egress doors lack tactile signs (with raised characters and braille).
- The service counter is higher than the maximum allowed.
- The interior doors from the main entrance main/exit to the northwest entrance/exit lack compliant door hardware.

#### **Order of Magnitude Cost Estimates**

 Miscellaneous corrective actions (Parking, signage, service counter, etc.): \$4,162

Total: \$4,162\*

\*Note: Cost to provide an accessible route to the building and an accessible entrance is not included.

A study is needed to determine the feasibility of providing an accessible route and an accessible entrance to the building.

#### **Best Practice and Inclusive Design**

Best practice and inclusive design recommendations include elements that are not required in the standards but may create enhanced experiences for all users.

- Recommend providing information on the website letting members of the public know that the building is not accessible.
- Recommend providing an intercom at an accessible location so a person in a wheeled mobility device, for example, could alert someone inside that they have arrived.
- Recommend providing a van accessible space at the loading dock since members of the public are allowed to park in this area.
- Recommend providing a sign at the top of the stairs (north side) indicating the location of the accessible route.
- Recommend adding contrasting strips at the edge of each step at all interior and exterior stairs.
- Recommend relocating the information signs located at the main entry door to avoid glare.

ID	Location	Floor	Room	n Element	Туре	Photo	Issues	Current Measure	Recommendations	Quantity	Price	Cost Estimation
A	approach and E	Entrance										
	Off-Street Parking Lot or Garage											
1	Lower Parking	Ext.		Off-Street Parking Lot or Garage	Visitor		otal # of parking otal # of designated van accessible spaces	7 -	Provide a van accessible space that is at least 96" wide with a marked access aisle that is at least 96" wide.  Locate sign with between 60" - 96" above the ground. Add the designation "Van Accessible" to the sign located at the van accessible space.	1	1850	\$1850
	Exterior Ram	o										
2	Ramp Near North West Entrance/Exit	Ext.		Exterior Ramp	N/A	Ru	unning slope > 1:12 (8.3%)	13.7%	See ID #3.	1	-	\$0
3	Ramp Near North West Entrance/Exit	Ext.		Exterior Ramp	N/A	Ha Ha Ha	unning slope > 1:12 (8.3%) andrails < 34" or > 38" above ramp surface. andrails not provided at both sides if rise is > 6" andrails do not extend 12" past top & bottom andrails have non-compliant cross section	22% 43.75" - -	A study is needed to determine the feasibility of providing an accessible route to the building.	1	-	\$0
	Exterior Stair											
4	Main Entrance/Exit	Ext.		Exterior Stair	N/A	Ha	andrails do not extend 12" from stair		Top: Ensure handrails extend horizontally above the landing for 12" min. beginning above the first riser nosing. Bottom: Ensure that the sloped bottom extension extends one tread depth minimum beyond last riser nosing in same direction as stair flight.	4	-	\$0

ID	Location	Floor Roor	n Element	Туре	Photo	Issues	Current Measure	Recommendations	Quantity	Price	Cost Estimation
5	Main Entrance/Exit	.5	Exterior Stair	N/A		. Handrail not provided on both sides	-	Provide a handrail on both sides.	1	-	\$0
	Entrance										
6	Main Entrance/Exit	.5	Entrance	Main Entrance	ALON MATERIAL PROPERTY AND THE PROPERTY	Entrance not on an accessible route	-	A study is needed to determine the feasibility of providing an accessible route to the building the building and to provide an accessible entrance.	1	-	\$0
7	Stair Near North West Entrance/Exit	Ext.	Entrance	Secondary Entrance		Entrance not on an accessible route	-	A study is needed to determine the feasibility of providing an accessible route to the building the building and to provide an accessible entrance.	1	-	\$0
	Access to Goo	ds and Services	<b>S</b>								
	Means of Egi	ress									
8	Main Entrance/Exit	1	Means of Egress		OFFICE STATE OF THE STATE OF TH	Tactile exit sign not provided	-	Ensure a tactile exit sign with raised characters and braille is provided at exit door. Mount sign between 48"- 60" above the finished floor located on the latch side of the door.	1	232	\$232
9	North West Entrance/Exit	1	Means of Egress	N/A		Tactile exit sign not provided	-	Ensure a tactile exit sign with raised characters and braille is provided at exit door. Mount sign between 48"- 60" above the finished floor located on the latch side of the door.	1	232	\$232

ID	Location	Floor Roon	n Element	Туре	Photo	Issues	Current Measure	Recommendations	Quantity	Price	Cost Estimation
	Interior Access Route										
10	To North West Entrance/Exit	1	Interior Access Route	N/A		Route < 36" wide	28.5"	Ensure that a clear width of 36" min. is maintained at the accessible route.	1	-	\$0
	Doors, Doory	ways, & Gates									
11	From Main Entrance/Exit to North West Entrance/Exit	1	Doors, Doorways, & Gates	Circulation		Hardware not operable with a closed fist	-	Provide hardware that can be operable with one hand and not require tight grasping, pinching, or twisting of the wrist.	1	484	\$484
12	From Main Entrance/Exit to North West Entrance/Exit	1	Doors, Doorways, & Gates	Circulation		Hardware not operable with a closed fist	-	Provide hardware that can be operable with one hand and not require tight grasping, pinching, or twisting of the wrist.	1	484	\$484
	Signage										
13	Along Driveway to Office	Ext.	Signage	Directional	OFFICE			Remove vegetation to ensure sign is visible to members of the public.	1	Labor	\$0
14	Sign at Intersection to RV's & Septic Discharge	Ext.	Signage	Directional	OFFICE CLOSED LOCKED WE 3:30 PM	Visual characters < 40" above ground	20"	Mount visual sign so that the baseline of the lowest character is 40" min. above the ground.	1	Labor	\$0

ID	Location	Floor	Room	Element	Туре	Photo	Issues	Current Measure	Recommendations	Quantity	Price	Cost Estimation
	Service Counter											
15	Counter - Main Entrance/Exit	1		Service Counter	N/A	Cour	nter > 36" high	42.5"	Provide a counter that is 36" max. above the ground or finished floor.	1	880	\$880
В	est Practice											
	Signage											
16	Stair to North West Entrance/Exit	Ext.		Signage	N/A				Recommend providing a sign indicating the location of the accessible route.	1	-	\$0
	Exterior Stair											
17	Stair to North West Entrance/Exit	Ext.		Exterior Stair	N/A				Recommend adding contrasting strips at the edge of each step at all interior and exterior stairs.	1		\$0
	Parking											
18	Loading Dock/Main Entrance to Office	Ext.		Parking	N/A			-	Recommend providing a van accessible space at this location since members of the public are allowed to park in this area.	1	-	\$0