# Luke's Love Playground



Town of Barnstable **ADA Transition Plan** 

September 2021



Institute for Human Centered Design

200 Portland Street, Boston, MA 02114 www.IHCDesign.org • info@IHCDesign.org 617-695-1225 voice/ tty

#### Background

Luke's Love Playground is located at 2377 Meetinghouse Way in West Barnstable, next to the West Barnstable Community Building and Lombard Field. There is one entrance/exit to the playground from the parking lot. Amenities include a toddler play area, a children's play area, two (2) sets of accessible play equipment, a swing set containing two (2) accessible chairs, and a climbing wall. There is also one (1) little library box and two (2) picnic tables.

#### **Key Accessibility Issues**

- Slightly steep walkways (left side of the playground).
- Lack of compliant hardware at the gate.
- Lack of an accessible route to the little library.

### **Order of Magnitude Cost Estimates**

#### Total: \$484

## **Best Practice and Inclusive Design**

Best practice and inclusive design recommendations include elements that are not required in the standards but may create enhanced experiences for all users.

Prepared by the Institute for Human Centered Design • www.IHCDesign.org

• Miscellaneous corrective actions (hardware, etc.): \$484

• Recommend providing some benches with backs and some with arms around the playground.

• Recommend providing detectable warnings at the curb ramp located near the accessible parking space.

### Town of Barnstable Luke's Love Playground

	Luke's Love Flayground											
ID	Location	Floor	Room	Element	Туре	Photo	Issues	Current Measure	Recommendations	Quantity	Price	Cost Estimation
A	pproach and E	Intrance										
	Exterior Access Route											
1	Route to Left of Entrance Next to Building	Ext.		Exterior Access Route	Walkway	Cross Runn	s slope > 1:50 (2.00%) ning slope > 1:20 (5%)	3.5% 6.5%	Reduce cross slope to be no steeper than 1:50 (2.00%). Reduce running slope to be no steeper than 1:20 (5%).	1	-	\$0
2	Little Library	Ext.		Exterior Access Route	Exterior	Acces	essible route not provided	-	Ensure an accessible route is provided.	1	Labor	\$0
	Entrance											
3	Exit	Ext.		Entrance	Gate	Hardw	lware not operable with a closed fist	-	Provide hardware that can be operable with one hand and not require tight grasping, pinching, or twisting of the wrist.		484	\$484
В	Best Practice											
	Detectable Warning											
4	Route From Parking Lot to Playground Entrance	Ext.		Detectable Warning	N/A				Recommend providing a detectable warning at this location.	1	-	\$0

	Route From Parking Lot to Playground Entrance	Ext.	Detectable Warning	N/A			Recommend providing a detect this location.
--	--	------	-----------------------	-----	--	--	---